

DAILY INSPECTION REPORT

Job No. 31-018-0810212955 (1)

BCWP - P1 - 001

Borrower Information
Blackfeet TribeDate 3-3, 2003

Name

P. O. Box 2809 Browning Mt. 59417Report No. 69 (2)Street County State Zip

Project Information

Type of Project Water intake - BCWPProject Location Lower Two Medicine LakeContractor(s) Name Stoddard ConstructionSuperintendent Dean StoddardWeather Conditions Cloudy, light snow +11° & +19°

Description of Work Accomplished The discharge mani-
fold has been assembled and
wrapped with polyethylene. All
concrete thrust blocks and valve
anchors have been poured. The en-
tire hole has been backfilled and
compacted. Minor finish grading
around pitless units remains.

Items of Interest Occurred Work has been suspended
until July 15, 2003

Delays or Work Restraining Orders

Change Orders

Additional Remarks

(Include problems, delays and controversies on orders)

BY

John M. M...
Resident Inspector

Note to Resident Inspector:

The original Daily Inspection report shall be submitted to the borrower at intervals not exceeding one (1) week with copies of the report furnished the project engineer, Contractor(s), and RUS.

(1) Assigned by RUS.

(2) Assigned by Resident Inspector in consecutive order beginning with No. 1.